



Inspection & Repair Costs

Mermet Springs has an on-site inspection station & repair shop for any equipment issue or quick fix to get back in the water fast.

Spools - \$12.00

Burst Disk - \$12.00

Standard LP Hose - \$50.00

Standard HP Hose - \$50.00

Fin Strap - \$8.00

SPG - \$98.00

PWR Inflator Hose - \$40.00, Replacement Power Inflator - \$52.00

Sherwood Regulator Service - 1st & 2nd Stages, Gauges & Computer - \$65.00 Plus Parts

Sherwood Regulator Inspection - \$25

Sherwood Regulator Service Rebuild Kits - \$25.00

Buoyancy Compensator - Clean, Service and Lube - \$35.00 Plus Parts

O2 Clean & Service - Scuba Cylinder Including K/DIN Valve - \$40.00 Plus Parts

O2 Clean Single Valve - \$20.00 Includes Parts

O2 Clean Crossover Manifold / Valve - \$35.00 Includes Parts

Visual Cylinder - \$15.00 Includes Parts

Tumble Cylinder - \$20.00

Minor Repairs - \$5.00 Plus Parts

Extraordinary Regulator Repairs & Cleaning May add \$10.00 for technician's time for extensive corrosion, soaking & ultra-sonic cleaning

Full Face Mask Rebuild - \$85.00 plus parts
